DAILY WORK ORDER	
Bossert Manufacturing	Work Period: 8/25/87
	OSC: Jack D. Harmon
WORK PLANNED/AUTHORIZED:  1.)Continue to clean out sumps #15A  & B. Begin sumps #1, #2 & #3.  2.)Set-up & initiate lasering in area #12 along w/sumps 35-42.  3.)Repair sump covers as needed.  4.)Cover the debris with visqueen & secure the doorways into areas #2 and #3.  4.)Sample areas #10 & #11 (1st floor) and begin sampling area #7 1st floor and 2nd floor pad.  5.)Fill in the trench, leading from the vacuum recovery system into the building, with sand.  6.)Open the vacuum recovery system to clean inside.	Yes No Continues  1.) (x) ( ) ( )  2.) (x) ( ) ( )  3.) (x) ( ) ( )  4.) ( ) ( ) (x)
<ul> <li>(3) Vans (1) Pick-up Truck</li> <li>(1) Decon trailer (3) Bobcats</li> <li>(1) Command Post Trailer</li> <li>(1) Crew Trailer (3) 12K Pools</li> <li>(1) Portable Eye Wash (2) Car</li> <li>(6) Radioes (1) 50K Pool</li> <li>(1) Water Treatment System  w/ appurtenances</li> <li>(2) High-Pressure Water Laser  w/hoses (1) Mini-Trackhoe</li> <li>(20) Propane tanks</li> <li>(1) Cascade System</li> <li>(1) 6-CY Dumpster (1) 3-in</li> <li>(4) Submersible Pumps: (3) 2-in</li> </ul>	COMMENTS:  427713  (4) Porta-Johns
(1) Response Manager ( (1) Laborer ( (1) Lab Technician (2) ( (8) Clean-up Technician (1)	(1) Foreman (3) (2) Foreman (2) (1) Field Clerk (5) Clean-up Technician (2) (1) Lab Tech. I
Y hard I	OSC Signature: Out D. H Date: 8 25 87